TECHNICAL BULLETIN GE-32

DATE:March 16, 2005MODEL YEAR:2005 & AFTERENGINE MODEL:J05CHASSIS MODEL:UD1300 ~ UD1800CSBULLETIN NUMBER:GE-32FILE IN THE GENERAL SECTION OF THE TECHNICAL BULLETIN BINDER

2005 & AFTER JO5 ENGINE VALVE CLEARANCE DATA

PURPOSE

To advise that the Valve Position Adjustment chart found on page MA-4-3 in the 2005 UD Truck Service Manual CD is incorrect. The chart identifies the incorrect valves to adjust during the 2 step valve adjustment procedure.

INSTRUCTIONS

Refer to the correct Valve Position Adjustment Chart found on page EN01-12 in the Engine Introduction section for the J05 Engine whenever it is necessary to check or adjust the valve clearance.

THE INFORMATION CONTAINED IN THIS BULLETIN SHOULD NOT BE INTERPRETED AS THE BASIS FOR WARRANTY CLAIMS							
FOR THE INDICATED PERSONNEL BELOW, PLEASE READ, INITIAL, AND ROUTE TO THE FOLLOWING:							
х	SERVICE MANAGER	Х	WARRANTY MANAGER	X SERVICE TECHNICIANS INITIAL BELOW:			
х	PARTS MANAGER	х	SHOP FOREMAN				