



## **SUBJECT: CARB “Certified Clean Idle” Label and Incomplete Vehicle Document replacements.**

Department: Service  
Section: Engine  
Model(s): All  
Model Year(s): 2008 and after  
Effective Date: 10/01/2017  
Form #: TSB EN-43  
Rev #: B  
Supersedes:

### **Purpose:**

Dealers may require replacement “Certified Clean Idle” label or VIN Plate due to accident damage, deterioration, etc. The Incomplete Vehicle Document may also get lost during transportation between the dealer and the body manufacturer.

This bulletin outlines the procedure that a dealer is to follow to obtain a replacement label, VIN plate or document.

### **Procedure:**

1. Complete the application for Vehicle Identification labels form # AFV11, page 1 of 2.
2. Complete the “Affidavit” found on form # AFV11, page 2 of 2.
3. Email the form to the listed email address on form # AVF11.
4. UDNA will process your request within 10 working days.
5. The dealer’s parts account will be charged a shipping and handling fee of \$60.00 for each label or document.

**The Information contained in this bulletin should not be interpreted as the basis for a warranty claim.**