

North America

SUBJECT: MID128 / PSID229 / FMI9 INACTIVE DTC

Department: Service Section: Engine Model(s): GH7

Model Year(s): 2011, 2012 & 2013 Effective Date: December 15, 2015

Form #: TB EN-58 Rev #: N/A Supersedes: N/A

Purpose: To advise technicians MID128 / PSID229 / FMI9 <u>INACTIVE</u> DTC is considered a nuisance code caused by the connection of TT2 to the vehicle.

Diagnostic trouble code (DTC) information

MID 128 PSID 229 FMI 9

Inactive diagnostic trouble code (DTC)

Fault tracing an inactive diagnostic trouble code (DTC) can be difficult. Field reports confirm this inactive DTC can be present and not relevant to any other DTC's. Do not attempt to troubleshoot this INACTIVE DTC. An investigation is currently active to determine the cause and correction of this inactive DTC.

Follow GD only if the code is ACTIVE.

The Information contained in this bulletin should not be interpreted as the basis for a warranty claim

Form#: TB EN-58 Page 1 of 1