



**DATE:** APRIL 3, 2000  
**MODEL YEAR:** 1995 ~ 2000  
**ENGINE MODEL:** FE6TA  
**BULLETIN #:** EC - 08  
**FILE IN THE ENGINE SECTION OF THE TECHNICAL BULLETIN BINDER**

### WATER PUMP DESIGN CHANGE FOR FE6TA ENGINES

#### PURPOSE:

To announce a design change in the water pump, effective with the 1999 production FE6TA engines.

#### SERVICE NOTICE:

As illustrated below, one mounting hole has been eliminated from the water pump beginning with FE6TA engines produced in 1999. Cylinder blocks and water pump gaskets manufactured after this change will still contain the mounting hole, although it is not necessary for water pump installations.

#### PARTS NOTICE:

- UD Genuine part numbers 21010Z5661 and 21010Z5661X (the newer style water pumps without the mounting hole) can be used in all applications.
- Installation of the older style water pump (with the mounting hole) requires the use of an additional bolt (part number 081208201E) to replace a newer style water pump.

UD GENUINE PART NUMBERS  
21010Z5661 AND 21010Z5661X

THIS MOUNTING HOLE IS  
ELIMINATED ON NEWER  
STYLE WATER PUMPS

