NISSAN DIESEL AMERICA. INC.

TECHNICAL BULLETIN ST-03

DATE: January 22, 2010

MODEL YEAR: AII
ENGINE: AII
CHASSIS MODEL: AII
BULLETIN NUMBER: ST- 03

FILE IN THE STEERING SECTION OF THE TECHNICAL BULLETIN BINDER

POWER STEERING MAINTENANCE ADVISORY


PURPOSE

To advise dealers of the importance of servicing the power steering system.

SERVICE RECOMMENDATION

The power steering system should be flushed and the filter changed as recommended in the maintenance schedule. Severe service conditions may necessitate shorter flush and filter change intervals. Refer to the maintenance section of the appropriate UD service manual for specific instructions for system flushing and filter change.

Note: While servicing medium duty trucks with the metal power steering fluid reservoir mounted to the rear cab mounting bracket, cut the vent hose at a 45° angle and insert it into the rear cab mounting bracket as shown in the illustration below.



THE INFORMATION CONTAINED IN THIS BULLETIN SHOULD NOT BE INTERPRETED AS THE BASIS FOR WARRANTY CLAIMS							
FOR THE INDICATED PERSONNEL BELOW, PLEASE READ, INITIAL, AND ROUTE TO THE FOLLOWING:							
х	SERVICE MANAGER	х	WARRANTY MANAGER	X SERVICE TECHNICIANS INITIAL BELOW:			
Х	PARTS MANAGER	Х	SHOP FOREMAN				